

Tobacco Barn
CT-102
Ponds Wood Road
Huntingtown, Calvert County
Rosemary Faya Prola
July 27, 2007

ADDENDUM

Section 7 DESCRIPTION

The buildings and structures that comprise the historic farming complex at 3010 Ponds Wood Road are situated at the top of a hill, with fields stretching to the south, southeast, north, and northeast. The dwelling and tobacco barn were documented in 1976. These buildings were photographed again in 2007 and the digital images are contained in the documentation for CT-1314, Ponds Wood Road Community. The barn was renovated in spring 2007; the roof has been painted and the wood siding replaced on the south and west elevations. The interior of the building is unchanged. A hole in the dirt floor in the northeast section is a "kiln," or cellar for storing potatoes and cabbages.

Also standing on the property is a number of outbuildings constructed by Allnut Reid after purchasing the land in 1940. A stable is situated to the east of the tobacco barn. The gable-roofed structure measures 14 by 21 feet and has a 10-by-14-foot shed addition on the west. The walls are covered in vertical wood siding and the roof is covered with standing-seam metal. There are windows in the shed on the west and north elevations and a door on the south elevation. The stable has small square openings in both gables and two doors on the south elevation. The stable was used as additional space for curing tobacco when not used for shelter for horses. A corn house is located to the northeast of the dwelling. The structure has a gable roof covered in standing seam metal and the vertical wood siding has peeling red paint. There is a double door on the west elevation. North of the dwelling are the ruins of a garage and chicken or brooder house. Northeast of the chicken house is a privy, also in ruins.

The buildings are in their original locations, and maintain their spatial relationships. With the exception of the tobacco barn which is in the process of renovation, all of the structures retain their original materials. The dwelling and corn house are in fair to good condition, with walls, roof, and foundation intact and apparently sound. The stable and stripping shed are in fair condition, with sound roofs and walls but covered with vegetation.

Photos 1, 2



CT-102
"TOBACCO BARN"
HUNTINGTOWN, MD
FRED FAYA

5 APRIL 2007

STABLE, SOUTH ELEVATION
1 OF 2



CT-102

"TOBACCO BARN"

FRED FAYA HUNTINGTOWN, MD

5 APRIL 2007

STABLE, ~~SOUTH~~ ELEVATION
WEST

2 OF 2

CT-102

Tobacco Barn
Huntingtown, MD
Ponds Wood Road, Willows Vicinity
Wayne Nield
Fall, 1976



~~P.22~~ P.22 58%

CT 102

5

Vertical file

Wayne L. Nield, II
Historic Sites Survey
Broomes Island, Maryland 20615
586-2050

CT-102
TOBACCO BARN, HUNTING TOWN, MD.
WAYNE NIELD FALL, 1976

1